



Company			
Attention	<i>Roger Duncombe / Jamie Anderson</i>	Ref	<i>00280.101</i>
Fax Number	<i>0207 583 4696</i>	Date	<i>12TH July 2001</i>
From	<i>Steve Pilcher</i>	Pages	<i>2</i>
Subject	<i>SNAGS AND OUTSTANDING WORKS</i>		

1. 2958 M4 / M15 - no details on this project anticipate this was carried out by sound specialists.
- ★ 2. 3142 H17 Kitchen Staff Area -
- i. Most of the existing PAVA cable (white) is not installed utilising metal cable ties. All new cabling (red) is metal cable tied.
 - ii. Junction box repaired but not part of original installation.
 - iii. PAVA speaker was moved.
- ★ 3. 3142 H17 Hadens Area -
- i. Cable ties as i. above.
 - ii. Speaker and cabling had been moved out of rest room.
 - iii. Corridor speakers had all been moved apparently during door entry system installation.

Note: For items 2 and 3 some metal ties have been installed to the existing cable, how far are we required to go?

3328 A19 - Drawing previously issued

3328 A35 - Drawing and snag previously issued

We trust this is satisfactory.

Yours faithfully
DIRECTION FIRE LTD

STEVE PILCHER
Sales Manager